



Hoover Heat Pump Tumble Dryer	
Aspect	Details
PSD Number	2505-0138
Product Type	Electrical appliances and equipment – Heat Pump Tumble Dryer
Product Identifiers	Affected Models: <ul style="list-style-type: none"><li>- 31900010, HTDBWH7A1TCE-80/</li><li>- 31900012, HBTDWH7A1TCE-80/</li><li>- 31900528, BHTD H7A1TCE-80</li><li>- 31900530, BHTDH7A1TCEB-80</li><li>- 31900531, BATDH7A1TCEB-80</li><li>- 31900536, BATD H7A1TCE-80</li><li>- 31900542, BATD H7A1TCER-80</li></ul>
Product Description	Hoover-branded built-in heat pump tumble dryer.
Country of Origin	Turkey
Counterfeit	No
Risk Type	Fire
Risk Description	<p>The products present a risk of fire as it is possible for an internal short circuit to occur within the tumble dryer during normal use. This can cause the tumble dryer to ignite, causing a fire.</p> <p>The products do not meet the requirements of the Electrical Equipment (Safety) Regulations 2016.</p>
Corrective Measures	<p>The manufacturer has initiated a modification programme.</p> <p>Owners are strongly advised to <b>STOP USING THE PRODUCT IMMEDIATELY</b> and contact the manufacturer to arrange for a modification to take place. The product should not be used until the modification has taken place. If the plug is accessible, switch off and unplug the appliance.</p> <p>For further information, including on how to register your product for modification, access the Haier product safety notice at the following link: <a href="#">Product Safety Issue – Hoover Direct</a></p>
Online Marketplace	N/A
Notifier	Office for Product Safety and Standards